

Paragraph	Page
5-3-6. Changeover Points (COPs)	5-3-19
5-3-7. Minimum Turning Altitude (MTA)	5-3-19
5-3-8. Holding	5-3-20

Section 4. Arrival Procedures

5-4-1. Standard Terminal Arrival (STAR) Procedures	5-4-1
5-4-2. Local Flow Traffic Management Program	5-4-3
5-4-3. Approach Control	5-4-3
5-4-4. Advance Information on Instrument Approach	5-4-4
5-4-5. Instrument Approach Procedure (IAP) Charts	5-4-5
5-4-6. Approach Clearance	5-4-27
5-4-7. Instrument Approach Procedures	5-4-29
5-4-8. Special Instrument Approach Procedures	5-4-31
5-4-9. Procedure Turn and Hold-in-lieu of Procedure Turn	5-4-31
5-4-10. Timed Approaches from a Holding Fix	5-4-34
5-4-11. Radar Approaches	5-4-37
5-4-12. Radar Monitoring of Instrument Approaches	5-4-38
5-4-13. Simultaneous Approaches to Parallel Runways	5-4-39
5-4-14. Simultaneous Dependent Approaches	5-4-41
5-4-15. Simultaneous Independent ILS/RNAV/GLS Approaches	5-4-43
5-4-16. Simultaneous Close Parallel PRM Approaches and Simultaneous Offset Instrument Approaches (SOIA)	5-4-45
5-4-17. Simultaneous Converging Instrument Approaches	5-4-52
5-4-18. RNP AR (Authorization Required) Instrument Procedures	5-4-52
5-4-19. Side-step Maneuver	5-4-54
5-4-20. Approach and Landing Minimums	5-4-54
5-4-21. Missed Approach	5-4-58
5-4-22. Use of Enhanced Flight Vision Systems (EFVS) on Instrument Approaches .	5-4-60
5-4-23. Visual Approach	5-4-64
5-4-24. Charted Visual Flight Procedure (CVFP)	5-4-65
5-4-25. Contact Approach	5-4-65
5-4-26. Landing Priority	5-4-66
5-4-27. Overhead Approach Maneuver	5-4-66

Section 5. Pilot/Controller Roles and Responsibilities

5-5-1. General	5-5-1
5-5-2. Air Traffic Clearance	5-5-1
5-5-3. Contact Approach	5-5-2
5-5-4. Instrument Approach	5-5-2
5-5-5. Missed Approach	5-5-3
5-5-6. Vectors	5-5-4
5-5-7. Safety Alert	5-5-4
5-5-8. See and Avoid	5-5-5
5-5-9. Speed Adjustments	5-5-5
5-5-10. Traffic Advisories (Traffic Information)	5-5-6
5-5-11. Visual Approach	5-5-6
5-5-12. Visual Separation	5-5-7
5-5-13. VFR-on-top	5-5-8
5-5-14. Instrument Departures	5-5-8
5-5-15. Minimum Fuel Advisory	5-5-9